From COMP AA

REPORT ABOUT THE MOTOR VEHICLES ACCIDENTS

1	Name of Police station	Kurunda Police Station Date 08/02/2025
2	CR NO/Tar no /Sde No	69/2025 Us 106(1),281, BNS
3	Date time and place of the	Date 07/02/2025 at 18:30 At Girgaon To Kurunda Road Near
	accident	Bundel Fakirchand Farm
4	Name of injured/Deceased	Deceased – Vijay Keshav Lokhande R/O Somthana TQ Basmat Dist Hingoli.
5	Name of hospital to which he/she was removed	
6	Number of vehicle and type of the vehicle	Motorcycle No. MH 38 AA 5597
7	Name and address of the driver of vehicle with particulars or Driving license of the side driver and the address of the	Motorcycle No. MH 38 AA 5597 Deceased – Vijay Keshav Lokhande R/O Somthana TQ Basmat Dist Hingoli.
	issuing authority of the side driving license the no of badge in case of public service vehicle and the address of the issuing authority of the side badge	
8	Name of address of owner of the vehicle as it stands date of accident	
9	Name and address of the insurance campony with whom the vehicle was insured and the divisional office the side insurance campony	
10	No of insurance policy/ insurance certificate and the date of validity of insurance policy/ insurance certificate	
11	Action taken if any and the result there of	As above
		Police Inspector Kurunda Police Station